

WhaleSpray

Technical Data Sheet

WS CRACK 3 (WS 3050 G)

Family: 3
Product code: 3050G00



Creation date: 02/11/2010
Review date: 29/04/2019
Página: 1 de 1

DESCRIPTION

WS 3050 G it's a fast drying degreaser, indicated for the pre-treatment of surfaces, before the non-destructive tests with penetrant liquids, also for removing penetrant liquid excess after use.

It is a very effective degreasing solvent mixture with quick drying. It doesn't contain in its composition aromatic or chlorinated solvents.

WS 3050 G penetrates and breaks up dirt and other pollutants to improve surfaces before non-destructive penetrant tests.

CHARACTERISTICS AND ADVANTAGES

- Dissolve quickly the dirt on the surfaces.
- Quick evaporation in order to optimize the cleaning process.
- Does not leave any type of residue.
- It is stable, does not affect or produce corrosion on metals.

HOW TO USE

- **1º.- SURFACES EXHAUSTIVE CLEANING WITH WS 3050 G/S**
Before you apply WS CRACK 1 (WS 1820 G/S) red penetrating liquid, you must do an exhaustive cleaning with degreaser and wait few seconds until his completely evaporation. Surface to inspect must be perfectly clean and free from any kind of residue, grease, oil, paints, oxide, etc.
- **2º.- WS CRACK 1 (WS 1820 G/S) PENETRATING APPLICATION**
Apply red penetrating on the area to inspect with a soften layer of spray, a brush or an impregnated duster. We recommend a penetrating time between 10-20 minutes; this will depend on ambient temperature. After this time, WS CRACK 1 (WS 1820 G/S), has penetrated on leaks and pores.
- **3º.- RED PENETRATING EXCESS REMOVAL**
Red penetrating excess will be removed with a duster or with low pressure water. Let it dry at ambient temperature or with hot air (maximum at 70°C).
- **4º.- WHITE DEVELOPER WS CRACK 2 (WS 1821 G/S) APPLICATION**
Apply a thin layer of white developer spray, thanks to his special formula drying will be very quick, and will defects will appear on surfaces in dark red color: leaks in red lines and pores as red spots.
- **5º.- Elimination of WS CRACK 1 (WS 1820 G/S) and WS CRACK 2 (WS 1821 G/S)**
WS CRACK 1 (WS 1820 G/S) and WS CRACK 2 (WS 1821 G/S) can be removed with pressured water or with a solvent.

FORMATS:
Bulk and spray



WhaleSpray
Spray everything

www.whalespray.com
P.I. Ametlla Park · c/ Aiguafreda, 24
08480 L'Ametlla del Vallès · Barcelona
Tel. 900 15 20 40

Síguenos en:

Empresa Certificada ISO 9001-ISO 14001
Company certified ISO 9001-ISO 14001